

UNION County
Groundwater Contamination Inventory
South Carolina - 2008

| Contamination Incident | Type of Contaminant | Source of Contamination | Bureau | U.S. EPA ID | Remarks |
|-------------------------------|---------------------|-------------------------|--------|--------------|---|
| Union County | | | | | |
| AMOCO STATION UNION | PETRO | UST | BLWM | | Site ID # 14944. RBCA Classification 1D4. Active corrective action. |
| BOBS GULF | PETRO | UST | BLWM | | Site ID # 12889. RBCA Classification 2BB1. Conducting investigation/Risk Assessment. |
| CABANISS SERVICE STATION | PETRO | UST | BLWM | | Site ID # 08985. RBCA Classification 2AA4. Active corrective action. |
| CARQUEST AUTO PARTS | PETRO | UST | BLWM | | Site ID # 19347. RBCA Classification 5B1. Conducting investigation/Risk Assessment. |
| CONSO PRODUCTS | VOC | PPL | BOW | | Site is in monitoring phase. Waste water line and basin. |
| ENMARK 560 | PETRO | UST | BLWM | | Site ID # 08995. RBCA Classification 3AA1. Conducting investigation/Risk Assessment. |
| EUBANKS GROCERY | PETRO | UST | BLWM | | Site ID # 08983. RBCA Classification 4AA7. Approved Monitored Natural Attenuation (MNA Awaiti. |
| GREERS SHELL 1 | PETRO | UST | BLWM | | Site ID # 08993. RBCA Classification 4BA8. Awaiting Funding. |
| GREGORYS STORE | PETRO | UST | BLWM | | Site ID # 08979. RBCA Classification 2AB4. Active corrective action. |
| HOT SHOTS GULF | PETRO | UST | BLWM | | Site ID # 12890. RBCA Classification 5A6. Contacted. |
| J H CROMER SITE | PETRO | UST | BLWM | | Site ID # 14564. RBCA Classification 2AA4. Active corrective action. |
| JOHNNIES MARKET & MORE | PETRO | UST | BLWM | | Site ID # 08986. RBCA Classification 3BA8. Awaiting Funding. |
| LIL CRICKET 216 | PETRO | UST | BLWM | | Site ID # 08996. RBCA Classification 3BD1. Conducting investigation/Risk Assessment. |
| MCCOY SERVICE CO INC | PETRO | UST | BLWM | | Site ID # 15360. RBCA Classification 3BA1. Conducting investigation/Risk Assessment. |
| SOUTHERN BELL UNION SOC | PETRO | UST | BLWM | | Site ID # 16443. RBCA Classification 2AA4. Active corrective action. |
| TIMKEN U.S. CORPORATION | PETRO, VOC | PPL | BLWM | SCD041387796 | In remediation phase. Formerly Torrington Tyger River Plant. |
| TORRINGTON COMPANY | PETRO | UST | BLWM | | Site ID # 08973. RBCA Classification 2BA4. Active corrective action. |
| UNION COUNTY MSW LANDFILL | VOC | LF | BLWM | | In assessment, monitoring, and remediation phases. Permit # 441001-1101. |
| UNION INDUSTRIAL SERVICES INC | PETRO | UST | BLWM | | Site ID # 08952. RBCA Classification 4AA9. CNFA. |
| UNION MILLS | PETRO, VOC | UST, S/L, AGT | BLWM | SCD047560859 | BLWM File # 51382. In assessment and monitoring phases. Plume is discharging to unnamed surface water body. |
| Total for Union | 20 | | | | |